

2014 FAA Worldwide Airport Technology Transfer Conference

REHABILITATION OF WATER-DAMAGED RUNWAY COMPOSITE PAVEMENTS

Seiya HAMA

Narita International Airport Corporation

Yoshitaka HACHIYA & Takaharu NISHIKAWA

SCOPE

JAPAN


Introduction

- ✿ South end 750 m of Runway A of NRT
 - ✿ Required to fully use
- ✿ Endmost 150 m section
 - ✿ Required to be more durable
- ✿ Composite pavement
 - ✿ Asphalt mixture (AM) layers placed on continuously reinforced concrete (CRC) slabs
 - ✿ Constructed in 2011 autumn - 2012 spring
- ✿ Some signs of distress
 - ✿ Appeared several months after construction


Introduction (Cont'd)

- ❧ Tentative repairs
 - ❧ Cut & overlay of AM in the same way
 - ❧ Some signs of distress were also appeared
- ❧ Causes of distress
 - ❧ Studied in several different ways
 - ❧ Classified into two kinds
 - ❧ Intrusion of water into AM
 - ❧ Low stability of AM
- ❧ Rehabilitation method
 - ❧ Cut & overlay of AM in the proposed way
 - ❧ Installation of water draining facilities

Narita International Airport





Composite Pavement: Plan



Composite Pavement

CRCP


Composite Pavement: Section



- Composite pavement
 - 100 mm thick AM
 - 50 mm thick DGA Surface
 - 50 mm thick SMA Binder
 - 350 mm thick CRC
- AM layers
 - Surrounded by concrete slabs

Signs of Distress on Surface

- Composite pavements
 - Open to aircraft operation in April 2012
- Some signs of distress
 - Appeared on surface a few months later



- Concaved surface
- Stains at construction joints
- Black & White spots
- Flow of AM around lighting

Signs of Distress (1)

- Dull sound at hammer tapping tests



- Flow of AM around airport lighting



Signs of Distress (2)

❧ Black spots



❧ White spots



❧ Stains at construction joints



Study on Causes of Distress

- Properties of cored samples taken from AM
 - Conditions of cores were visually inspected.
 - Various properties were measured in the cores.
 - Chemical compositions of the spots and stains were identified.
- Structural conditions of pavements
 - The response of composite pavement to aircraft loads was analyzed by using 3D-FEM

Conditions and Properties (1)

❧ Fracture of AM

- ❧ Marks of slippage between AM and CRC
- ❧ Fractured planes in AM and at AM interface



❧ Water in AM

- ❧ Found between AM and CRC, and in the fractured planes.



Water content of AM (unit: %)

Area	Surface	Binder
Dull sounding	0.43	0.81
Sound	0.16	0.26

Conditions and Properties (2)

❧ Thickness

- ❧ Ave. AM thickness in concave areas is 33, 40 mm in surface, binder course, respectively

❧ Dynamic stability of surface course AM

- ❧ Dynamic stability (DS) satisfied the specification of $DS > 300$ times/mm

Dynamic stability

Sound Area		Dull sounding area	
413	458	510	960


(unit: times/mm)

Chemical Compositions

- ❧ Black spots
 - ❧ Composed of the same substances as asphalt emulsion and asphalt
- ❧ White spots
 - ❧ Recognized as inorganic and containing calcium carbonates
 - ❧ No obvious differences at fractured planes and others
- ❧ Stains at construction joint
 - ❧ Made of the same substances as white spots

Structural Analysis with 3D-FEM

✎ Pavement modeling




✎ Analytical conditions


CASE	Temperature	Bonding at interface
1	Surface = Binder	Fully bonded
2	Surface > Binder	Fully bonded
3	Surface > Binder	Separated

Results of Analysis (1)


- ✎ In CASEs 1 and 2, stress between AM and CRC is larger than AMs.
- ✎ In CASE 3, stress between AMs is much larger than AM and CRC.



CASE 1




CASE 2




CASE 3

Results of Analysis (2)


- Stress in CASE 3 is larger than CASEs 1 and 2.
- Little risk of separation between AMs as long as the bonding is secured.



CASE 1



CASE 2



CASE 3

Causes of Signs of Distress

- ❧ Dull sound at hammer tapping tests
 - ❧ Insufficient stability of AM
 - ❧ DS was lower than the new standard
 - ❧ Air void was below the standard
 - ❧ Water remained in AM
 - ❧ Might cause blistering
- ❧ Black & white spots and stains at joints
 - ❧ Asphalt exfoliation & efflorescence from concrete were found
- ❧ Flow of AM around airport lighting
 - ❧ Insufficient stability of AM

Causes of Major Distress


- ❧ Intrusion of water into AM
 - ❧ AM layers with low air voids were surrounded by CRC on the bottom and all sides.
 - ❧ Once water has permeated the pavement, it cannot naturally escape from it.
- ❧ Low stability of AM
 - ❧ Stability of AM insufficient to carry heavy aircraft loads resulted in plastic deformation progressed by repeated load applications.

Rehabilitation Plan (1)

❧ Countermeasures against Intrusion of water into AM (1)

❧ Pavement structure

- ❧ PM DGA of 60 mm thickness and 4.5% air void
- ❧ PM drainage asphalt of 40 mm thickness and 20% air void (about 0.01 cm/s permeability)
- ❧ Emulsified PM asphalt tack coat




Rehabilitation Plan (2)

Countermeasures against Intrusion of water into AM (2)

Water draining facilities

- Transverse open grooves of 6 – 10 mm width
- Wider ditches filled with drainage asphalt



Rehabilitation Plan (3)

Countermeasures against low stability of AM

- Asphalt mixture with DS > 3,000 times/mm is required.
 - PMA Type II is adopted for surface course
 - PMA Type H is adopted for binder course

Item	Straight (40 – 60)	PMA	
		II	H
Softening point (°C)	47 – 55	> 56.0	> 80.0
Ductility at 15°C (cm)	> 10	> 50	-
Toughness at 25°C (Nm)	-	> 8.0	> 20
Tenacity at 25°C (Nm)	-	> 4.0	-

Summary

- Causes of distress in composite pavements
 - Intrusion of water in composite pavements
 - Low stability of asphalt mixtures
- Rehabilitation methods
 - Pavement structure
 - Water draining facilities
 - Asphalt mixtures



A photograph of an airport runway at night. The runway is illuminated by a series of red lights along its edge and center. The sky is dark blue, and the horizon shows some distant lights and structures.

Thank you for your attention.

<http://www.naa.jp/en/index.html>

<http://www.scopenet.or.jp/main/e/index.html>